

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.8

0.1

N/A

N/A

N/A

N/A

N/A

Main Street: HAWTHORNE LN **Cross Street: KENNON ST** Intersection ID: 12063 Location: SW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 6FBC8ED5B6A4 Ramp Type: Perp **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

Flare Traversable RT?

Flare Type RT

Data

61.0

41.0

N/A

N/A

N/A

N/A

N/A




Street 1 Name	KENNON ST
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

	Possible Solutions:	Compli	ance	Description
200	Remove & Replace Entire Ramp.	N/A	Ram	c Length (in)
	•	No	Ram	o Width (in)
		N/A	Flare	Type LT
		N/A	Flare	Slope LT (%)
11.00		N/A	Flare	Traversable LT
No.		N/A	Land	ing Length (in)
	Surveyor Notes:	N/A	Land	ing Width (in)
	N/A	N/A	Land	ing Slope (%)
27.5		N/A	Land	ing X Slope (%
		N/A	Land	ing Curb? (Y/N
3		N/A	Share	ed Landing?
1	PROW/ADA:	N/A	Gutte	er Ponding?
200	Not Found, R304.5.1	N/A	Gutte	er Lip Ht (in)
		N/A	Paint	ed X Walk1?
APP 19.			X Wa	lk 1 Direction
		N/A	X Wa	ılk 1 Width (in)
			X Wa	lk 1 Slope (%)
			X Wa	lk 1 X Slope (%
		N/A	Ram	o inside XWalk
			_	(0/)

			- 6
	-		
			*
	1		1
The state of			





Flare Traversable LT?

