

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



, , , , , , , , , , , , , , , , , , ,									
Intersection ID: 49003	49003 Main Street: STEELE_CREEK_RD			Street:	STEELECROFT_PY	Location:	SE		
ADA ID: 6FD9E8E168BE	68BE Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		
		Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	9.3
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
L L L L L L				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
SUEELEOROFUE	Sall in	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	ARE IN LIVE	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	ATTACK AND AND A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
PROW/ADA: R304.2.2				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
II . / II .	ALC NO DE				X Walk 1 Direction	To N		X Walk 2 Direction	To W
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	STEELECROFT PY				X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	1.5
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	0.6
Street 2 Name	STEELE CREEK RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.3	N/A	Clear Space?	N/A
					Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

