


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 13345	Main Street: COMMONWEALTH_AV	Cross Street: THOMAS_AV	Location: NW
ADA ID: 6FF4C42F82BA	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	60.0
			Yes	Ramp Width (in)	49.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To S
			N/A	X Walk 1 Width (in)	144.0
				X Walk 1 Slope (%)	0.3
				X Walk 1 X Slope (%)	2.0
			N/A	Ramp inside XWalk1?	Yes
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2, R304.5.3</p>			N/A	Ramp Slope (%)	9.3
			No	Ramp XSlope (%)	3.2
			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
			N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk2?	N/A
				X Walk 2 Direction	N/A
			N/A	X Walk 2 Width (in)	N/A
				X Walk 2 Slope (%)	N/A
				X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
<p>Total Cost:</p> <p>\$ 1850.00</p>			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

