

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

57.0

59.0

2.4

1.9

1.2

5.2

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 7195 Main Street: REAGAN DR **Cross Street: TOM HUNTER RD** Location: SW **Overall Compliance: No** Severity Score: 46.25 ADA ID: 70111C004680 Ramp Type: Combination1 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Data

61.5

59.5

14.2

2.1

48.0

43.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



StopSign Street 1 Name Stop Condition-Street 1 TOM HUNTER RD N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes No No N/A No Surveyor Notes: N/A **RP & RT RP < 5%** N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3, N/A R304.3.2 N/A N/A N/A N/A N/A



Total Cost:



1800.00

Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? N/A To SE N/A X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 6.6 X Walk 2 Slope (%) N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 3.5 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 10.5 Curb Slope (%)