

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 54159	Main Street: OAKDALE_RD	Cross Street: SANDERS_FARM_LN	Location: N
ADA ID: 7020BB64231C	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 15.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	104.5	Yes	Ramp Slope (%)	6.2
	Remove & Replace Gutter.		Yes	Ramp Width (in)	60.5	No	Ramp XSlope (%)	4.7
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	5.8	Yes	Flare Slope RT (%)	7.5
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
			Yes	Landing Length (in)	60.5	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	60.5	Yes	DWS Contrast?	Yes
			No	Landing Slope (%)	3.4	Yes	DWS Length (in)	24.0
			No	Landing X Slope (%)	3.5	Yes	DWS Full Width?	Yes
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	8.5
PROW/ADA:		Not Found, R304.5.3, R304.2.2-Perp, R304.3.2-Para, R305.2, R302.7.2	N/A	Shared Landing?	No			
			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.1
			No	Gutter Lip Ht (in)	2.0	No	Gutter X Slope (%)	3.7
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	N/A	N/A	Clear Space?	Yes
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good

Street 1 Name	OAKDALE RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

