cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8266 Main Street: CATHERINE_SIMMONS_AV Cross Street: MADRID_ST								Location:	NE	
ADA ID: 702EB26C2EFB Ramp Type: PerpDiag										
Codes/Mitigation Info/Possible Solution				minutar	nitial Pass/Fail: Fail Overall Compliance: No Severity Score Field Measurements/Component Compliance					
Possible Solutions:										
					-					Data
		Remove & Replace Curb R	•	Vith	N/A	Ramp Length (in)	38.5	No	Ramp Slope (%)	8.7
		Two New Directional Ramps or Equivalent.	ps or		Yes	Ramp Width (in)		No	Ramp XSlope (%)	2.5
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Same and the second second		3			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	E PAS				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	THERNE SIMMONS AV	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A CONTRACTOR		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
El Commence Type					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6	6				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
And the				N/A	Shared Landing?	N/A				
	1 Sum	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304	4.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Ministry Bar	·····,····,·····,·····,······			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
						X Walk 1 Direction	To W		X Walk 2 Direction	To S
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	MADRID ST	-				X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	2.2
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	4.2
Street 2 Name	CATHERINE SIMMONS AV				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None					Road Slope (%)	1.1	N/A	Clear Space?	N/A
	None					Road X Slope (%)	7.8	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	7.0 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	¢ 2	200.00	11/5	Obstruction Type	17/4		Storm Grate/Utility Type	11/2
			φυ	200.00			N/A		otom orale/ounty type	N/A
							IN/A	1		IN/A

Yes Surface Condition? (G/P)

Good

