


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10899	Main Street: AUTEN_ST	Cross Street: DUCKWORTH_AV	Location: N
ADA ID: 7056AC7101B0	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 61.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	56.0	No	Ramp Slope (%)	12.5
			No	Ramp Width (in)	28.0	No	Ramp XSlope (%)	3.3
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
<p>Street 1 Name </p>								

Street 1 Name	AUTEN ST
Stop Condition-Street 2	StopSign
Street 2 Name	DUCKWORTH AV
Stop Condition-Street 1	None

