

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9739	Main Street: FAIRFIELD_ST	Cross Street: PATTON_AV	Location: NW
ADA ID: 705932A6F8CA	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 15	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.
Remove & Replace Gutter.**

Surveyor Notes:

N/A

PROW/ADA:

**Not Found, R305.1.4, R305.2,
R302.7.2, R304.5.4**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	121.0	N/A	Grade Break?	N/A
Yes	Ramp Width (in)	59.0	N/A	Grade Break Slope (%)	0.0
Yes	Ramp Slope (%)	3.4	N/A	Grade Break XSlope (%)	0.0
Yes	Ramp XSlope (%)	1.7			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	61.5	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.4	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	2.3	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	4.3
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	4.3
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	5.3
No	Gutter Lip Ht (in)	0.3	Yes	Gutter X Slope (%)	2.6
N/A	Painted X Walk1?	No		Road Slope (%)	0.3
	X Walk 1 Direction	To SW		Road X Slope (%)	3.3
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	3.3	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	22.3

Total Cost: \$ 2350.00

Street 1 Name	PATTON AV
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

