

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11483 Main Street: E\_17TH\_ST Cross Street: N\_CALDWELL\_ST Location: N

ADA ID: 70779F61E7AF Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

E 17TH ST StopSign N CALDWELL ST None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data No N/A Ramp Length (in) 66.0 Ramp Slope (%) 17.2 No Ramp XSlope (%) Yes Ramp Width (in) 65.0 3.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A DWS Provided? N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) 1.0 N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SW X Walk 2 Direction To SE N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 2.5 X Walk 2 Slope (%) 4.9 X Walk 2 X Slope (%) X Walk 1 X Slope (%) 2.0 0.9 N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) 1.4 N/A Clear Space? N/A N/A Road X Slope (%) 4.5 Clear Space to XWalk (in) N/A

N/A

N/A

N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

Good







N/A

Any Obstructions?

**Obstruction Type**