

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.6

3.7

N/A

10.6

Yes

No

No

N/A

No

N/A

9.7

3.5

N/A

N/A

N/A

N/A

N/A

N/A

Yes

Intersection ID: 7368 Main Street: BURCH_DR Cross Street: DISTRIBUTION_CENTER_DR Location: NW

ADA ID: 709BA42034AA Ramp Type: Perp Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 27.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

No

N/A

No

N/A

N/A

N/A

N/A

No

No

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Data

61.0

48.0

9.0

Yes

N/A

N/A

N/A

N/A

No

No

Yes

0.0

No

To E

N/A

5.0

1.0

N/A

N/A

Sloped



Street 1 Name
Stop Condition-Street 2
None
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:

Remove & Replace Entire Ramp.
Remove & Replace Gutter.

Surveyor Notes:


N/A

PROW/ADA:

Not Found, R304.5.3, R304.2.1,
R304.2.2-Perp, R304.3.2-Para,
R304.2.3, R305, R302.7, R304.5.4

R304.2.2-Perp, R304.3.2-Para, R304.2.3, R305, R302.7, R304.5.4





Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Flare Traversable LT?

Flare Type LT

N/A

Yes

N/A

N/A

N/A

No

No

No

No

N/A

N/A

No

Yes

N/A

N/A

N/A



