cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



ADA ID: 70A30832433F Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5 Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance Possible Solutions: Compliance Description Data Compliance Description Data	Intersection ID: 31424 Main Street: MT_HOLLY-HUNTERSVILLE_RDCross Street: GARRON_POINT_DR Location: N						
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance Possible Solutions: Compliance Description Data Compliance Description Data							
Possible Solutions: Compliance Description Data Compliance Description Data		111111111035/1	· · · ·				
			0				Dete
Remove & Replace Entire Ramp. N/A Ramp Length LT (in) 56.5 N/A Ramp Length RT (in) 31.0 Yes Ramp Width LT (in) 56.0 Yes Ramp Width RT (in) 52.5		Remove & Replace Entire Ramp.					
		and the second				1 ()	
		Mar.					
N/A Ramp Length (in) 41.0 No Ramp Slope (%) 9.9 No Ramp Width (in) 47.0 No Ramp XSlope (%) 3.1						,	
No No Ramp Vidur (in) 47.0 No Ramp Xslope (%) 3.1 Surveyor Notes: N/A Flare Type LT N/A Flare Type RT N/A		Suprover Netes:					
Building N/A Plate Type L1 N/A Plate Type L1 N/A N/A N/A Plate Type L1 N/A Plate Type L1 N/A						51	
N/A N/A N/A N/A N/A N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A	Co multiple	N/A					
N/A Hale Have sable L1? N/A Hale Have sable L1? N/A N/A Landing Length (in) N/A DWS Provided? N/A	THE STATE OF THE S	*					
N/A Landing Vidth (in) N/A DWS Contrast? N/A	Installate						
PROW/ADA: N/A Landing Slope (%) N/A N/A DWS Length (in) N/A	THE HOLE	PROW/ADA:					
Not Found, R304.5.1, R304.2.2, N/A Landing X Slope (%) N/A DWS Full Width? N/A	- Canon - Cano	and the second		- · · · <i>,</i>		0 ()	
R304.5.3 N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A							
N/A Shared Landing? N/A		Noo Holo					
N/A Gutter Ponding? N/A Gutter Slope (%) N/A				-		Gutter Slope (%)	N/A
Street 1 Name StopSign N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A	Street 1 Name Stor	Sign		-		,	
Stop Condition-Street 1 GARRON POINT DR N/A Painted X Walk1? No N/A Painted X Walk2? N/A		-		,		1 ()	
Street 2 Name N/A X Walk 1 Direction To NE X Walk 2 Direction N/A	-						
Stop Condition-Street 2 N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A							
X Walk 1 Slope (%) 0.5 X Walk 2 Slope (%) N/A							
X Walk 1 X Slope (%) 4.1 X Walk 2 X Slope (%) N/A							
Total Cost: \$ 1800.00 N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A		Total Cost: \$18	00.00 N/A				
Road Slope (%) N/A Clear Space? N/A					N/A		
Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A					N/A N/A	•	N/A
N/A Any Obstruction? N/A	the second se				N/A	,	N/A
Obstruction Type		A MARINE STALL MAN	14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			-	
N/A			De HARK				N/A
N/A Storm Grate/Utility Hazard? N/A					N/A	Storm Grate/Utility Hazard?	N/A
N/A Storm Grate/Utility Type			1			•	IN/A
N/A			200				N/A
Yes Surface Condition? (G/P) Good					Yes	Surface Condition? (G/P)	Good
Curb Slope (%) 11.4		And Do the				Curb Slope (%)	11.4