cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17607 Main Str	ntersection ID: 17607 Main Street: BRIGHTON_BROOK_DR Cross Street: GARDEN_GATE_CT							Ν
							Location:	
ADA ID: 70B7723C3F1B Ramp Type: PerpDiag		initial Pa	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	92.0	Yes	Ramp Slope (%)	7.1
	Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.3
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the markers			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second second			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
material and a second	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	, i i i i i i i i i i i i i i i i i i i		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
A CONTRACT AND A CONTRACT				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name BRIGHTON BROOK DR				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	0.8
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	5.9
Street 2 Name GARDEN GATE CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 StopSign				Road Slope (%)	2.0	N/A	Clear Space?	N/A
				Road X Slope (%)	4.7	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P) Good

