

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15162	Main Str	eet: EWING_AV	Cross Street: IDEAL_WY					Location:	NE
ADA ID: 70C70B645A6B Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	. Incal Company	Possible Solutions:	Compliance Description Data			Compliance Description		Data	
		Remove & Replace Entire Ramp.	N/A	Ramp Len	gth (in)	76.0	No	Ramp Slope (%)	9.0
and the second	I I		Yes	Ramp Wid	th (in)	62.0	Yes	Ramp XSlope (%)	1.8
			N/A	Flare Type	e LT	N/A	N/A	Flare Type RT	N/A
	States - States		N/A	Flare Slop	e LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Trav	ersable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Le	ength (in)	N/A	N/A	DWS Provided?	N/A
	- And Barris	Surveyor Notes:	N/A	Landing W	/idth (in)	N/A	N/A	DWS Contrast?	N/A
	the and the	N/A	N/A	Landing S	lope (%)	N/A	N/A	DWS Length (in)	N/A
DEAL WY			N/A	Landing X	Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing C	urb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Mary Mary		N/A	Shared La	nding?	N/A			
		PROW/ADA:	N/A	Gutter Por	nding?	N/A	N/A	Gutter Slope (%)	N/A
	A	Not Found, R304.2.2	N/A	Gutter Lip	Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X	Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 D	Direction	To W		X Walk 2 Direction	N/A
			N/A	X Walk 1 V	Vidth (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	EWING AV			X Walk 1 S	Slope (%)	1.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign			X Walk 1 X	K Slope (%)	1.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp insid	de XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slop	e (%)	N/A	N/A	Clear Space?	N/A
				Road X Sl	ope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstr	uctions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstructio	n Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

