

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5367	Main Street: HUBBARD RD			Cross Street: MALLARD_CREEK_RD				Location: N		
ADA ID: 70F826EE636C Ramp Type: Perp			muar	Initial Pass/Fail: Fail Overall Compliance: No					12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	To all	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data	
		Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	7.9	
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.9	
	11/			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	1/4			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	1 1	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	will be an			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
· CHARTER C				N/A	Shared Landing?	N/A				
	A CONTRACT	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	A we we	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	A State			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	1.00				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	HUBBARD RD				X Walk 1 Slope (%)	6.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.7		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good





