

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18834	soction ID: 19934 Main Stroot: CLENHAM DD				Cross Street: MILEORD RD				NW
	Main Street: GLENHAM_DR			Cross Street: MILFORD_RD			Location:		
ADA ID: 710909EA80FE	710909EA80FE Ramp Type: Directional1		Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Can and	Possible Solutions:		Compliance Description			Data Compliance Description		Data
	and the second	Remove & Replace Entire Ram	ıp.	N/A	Ramp Length (in)	70.0	N/A	Grade Break?	N/A
and the second	Real Lis	-	-	Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0
the same is	ANA			Yes	Ramp Slope (%)	5.0	N/A	Grade Break XSlope (%)	0.0
	Non At			No	Ramp XSlope (%)	5.7			
	P. TE SAL			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	and the second			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	N N ISA	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E.		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
MILFORD_RD	Par Par Par			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	and the second second	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	Ething .			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
A CONTRACTOR OF THE OWNER OWNER OF THE OWNER OWNE OWNER OWNE	and the second			N/A	Painted X Walk1?	No		Road Slope (%)	4.3
Street 1 Name	MILFORD RD				X Walk 1 Direction	To SE		Road X Slope (%)	2.3
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.3	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	29.6

