

Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 10040726	Main Street: W_TRADE_ST	Cross Street: N/A	Location: W
ADA ID: 7127B2081541	Ramp Type: Para	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 10

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

ACCESS AISLE RAMP

PROW/ADA:

R305

Street 1 Name	W_TRADE_ST
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Total Cost: \$ 1600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	N/A	N/A	Ramp Length RT (in)	116.0
N/A	Ramp Width LT (in)	N/A	Yes	Ramp Width RT (in)	54.0
N/A	Ramp Slope LT (%)	N/A	Yes	Ramp Slope RT (%)	4.7
N/A	Ramp XSlope LT (%)	N/A	Yes	Ramp XSlope RT (%)	1.3
Yes	Landing Length (in)	60.0	No	DWS Provided?	No
Yes	Landing Width (in)	60.0	N/A	DWS Contrast?	No
Yes	Landing Slope (%)	0.9	N/A	DWS Length (in)	N/A
Yes	Landing X Slope (%)	1.7	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	Yes	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.7
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.3
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	0.8

