

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21728Main Street:BRYNHURST\_DRCross Street:WATERCREST\_RDLocation:SWADA ID: 7167D3EF3803Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WATERCREST RD None BRYNHURST DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.3

Total Cost: \$ 3200.00

| Compliance Description |                       | Data  | Comp | liance Description          | Data  |
|------------------------|-----------------------|-------|------|-----------------------------|-------|
| N/A                    | Ramp Length (in)      | 72.0  | Yes  | Ramp Slope (%)              | 5.2   |
| Yes                    | Ramp Width (in)       | 48.0  | No   | Ramp XSlope (%)             | 12.9  |
| N/A                    | Flare Type LT         | N/A   | N/A  | Flare Type RT               | N/A   |
| N/A                    | Flare Slope LT (%)    | N/A   | N/A  | Flare Slope RT (%)          | N/A   |
| N/A                    | Flare Traversable LT? | N/A   | N/A  | Flare Traversable RT?       | N/A   |
| N/A                    | Landing Length (in)   | N/A   | N/A  | DWS Provided?               | N/A   |
| N/A                    | Landing Width (in)    | N/A   | N/A  | DWS Contrast?               | N/A   |
| N/A                    | Landing Slope (%)     | N/A   | N/A  | DWS Length (in)             | N/A   |
| N/A                    | Landing X Slope (%)   | N/A   | N/A  | DWS Full Width?             | N/A   |
| N/A                    | Landing Curb? (Y/N)   | N/A   | N/A  | DWS Offset (in)             | N/A   |
| N/A                    | Shared Landing?       | N/A   |      |                             |       |
| N/A                    | Gutter Ponding?       | N/A   | N/A  | Gutter Slope (%)            | N/A   |
| N/A                    | Gutter Lip Ht (in)    | N/A   | N/A  | Gutter X Slope (%)          | N/A   |
| N/A                    | Painted X Walk1?      | No    | N/A  | Painted X Walk2?            | No    |
|                        | X Walk 1 Direction    | To NE |      | X Walk 2 Direction          | To NW |
| N/A                    | X Walk 1 Width (in)   | N/A   | N/A  | X Walk 2 Width (in)         | N/A   |
|                        | X Walk 1 Slope (%)    | 3.2   |      | X Walk 2 Slope (%)          | 6.1   |
|                        | X Walk 1 X Slope (%)  | 8.5   |      | X Walk 2 X Slope (%)        | 6.4   |
| N/A                    | Ramp inside XWalk1?   | N/A   | N/A  | Ramp inside XWalk2?         | N/A   |
|                        | Road Slope (%)        | 10.5  | N/A  | Clear Space?                | N/A   |
|                        | Road X Slope (%)      | 0.4   | N/A  | Clear Space to XWalk (in)   | N/A   |
| N/A                    | Any Obstructions?     | N/A   | N/A  | Storm Grate/Utility Hazard? | N/A   |
|                        | Obstruction Type      |       |      | Storm Grate/Utility Type    |       |
|                        |                       | N/A   |      |                             | N/A   |
|                        |                       |       | Yes  | Surface Condition? (G/P)    | Good  |





