

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45183Main Street:WESTON\_GLEN\_DRCross Street:COMMUNITY\_HOUSE\_RDLocation:NWADA ID: 71EB657AEFF6Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:21.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WESTON GLEN DR StopSign COMMNITY HOUSE RD Signal Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data					
					6.9
	,				6.4
	. , ,		l	,	N/A
	,,		l	••	N/A
			l	. , ,	N/A
			l		N/A
	3 3 ( )		l		N/A
	• ( )		l		N/A
	• ,		l	3 ( )	N/A
	0 1 ( )		l		N/A
	• ,			2110 0001 ()	
	· ·	N/A	N/A	Gutter Slope (%)	N/A
	· ·		l	,	N/A
	. , ,		l	. ,	Yes
	X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	114.0
	X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	6.8
	1 ( )	5.8		1 ( )	2.1
N/A		N/A	N/A	. ( )	Yes
	•	5.9	N/A	Clear Space?	N/A
	Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
	··	N/A		, ,,	N/A
			Yes	Surface Condition? (G/P)	Good
	N/A	N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A Any Obstructions?	Compliance         Description         Data           N/A         Ramp Length (in)         60.0           No         Ramp Width (in)         41.0           N/A         Flare Type LT         N/A           N/A         Flare Slope LT (%)         N/A           N/A         Flare Traversable LT?         N/A           N/A         Landing Length (in)         N/A           N/A         Landing Length (in)         N/A           N/A         Landing Width (in)         N/A           N/A         Landing Slope (%)         N/A           N/A         Landing X Slope (%)         N/A           N/A         Shared Landing?         N/A           N/A         Gutter Ponding?         N/A           N/A         Gutter Lip Ht (in)         N/A           N/A         Painted X Walk1?         No           X Walk 1 Direction         To SE           N/A         X Walk 1 Width (in)         N/A           X Walk 1 Slope (%)         1.8           X Walk 1 X Slope (%)         5.8           N/A         Road Slope (%)         5.9           Road X Slope (%)         3.9           N/A         Obstruction Type	Compliance         Description         Data         Compliance           N/A         Ramp Length (in)         60.0         Yes           No         Ramp Width (in)         41.0         No           N/A         Flare Type LT         N/A         N/A           N/A         N/A         N/A <t< th=""><th>ComplianceDescriptionDataComplianceDescriptionN/ARamp Length (in)60.0YesRamp Slope (%)NoRamp Width (in)41.0NoRamp XSlope (%)N/AFlare Type LTN/AN/AFlare Type RTN/AFlare Slope LT (%)N/AN/AFlare Type RTN/AFlare Traversable LT?N/AN/AFlare Traversable RT?N/ALanding Length (in)N/AN/ADWS Provided?N/ALanding Width (in)N/AN/ADWS Contrast?N/ALanding Slope (%)N/AN/ADWS Full Width?N/ALanding Slope (%)N/AN/ADWS Full Width?N/ALanding Curb? (Y/N)N/AN/ADWS Offset (in)N/AShared Landing?N/AN/ADWS Offset (in)N/AGutter Ponding?N/AN/AGutter Slope (%)N/AGutter Lip Ht (in)N/AN/AGutter Slope (%)N/APainted X Walk1?NON/APainted X Walk2?X Walk 1 DirectionTo SEX Walk 2 DirectionN/AX Walk 1 Width (in)N/AN/AX Walk 2 Slope (%)X Walk 1 Slope (%)1.8X Walk 2 Width (in)X Walk 2 Slope (%)5.8X Walk 2 X Slope (%)N/AAny Obstructions?N/AN/AClear Space to XWalk (in)N/AAny Obstructions?N/AN/AStorm Grate/Utility Type</th></t<>	ComplianceDescriptionDataComplianceDescriptionN/ARamp Length (in)60.0YesRamp Slope (%)NoRamp Width (in)41.0NoRamp XSlope (%)N/AFlare Type LTN/AN/AFlare Type RTN/AFlare Slope LT (%)N/AN/AFlare Type RTN/AFlare Traversable LT?N/AN/AFlare Traversable RT?N/ALanding Length (in)N/AN/ADWS Provided?N/ALanding Width (in)N/AN/ADWS Contrast?N/ALanding Slope (%)N/AN/ADWS Full Width?N/ALanding Slope (%)N/AN/ADWS Full Width?N/ALanding Curb? (Y/N)N/AN/ADWS Offset (in)N/AShared Landing?N/AN/ADWS Offset (in)N/AGutter Ponding?N/AN/AGutter Slope (%)N/AGutter Lip Ht (in)N/AN/AGutter Slope (%)N/APainted X Walk1?NON/APainted X Walk2?X Walk 1 DirectionTo SEX Walk 2 DirectionN/AX Walk 1 Width (in)N/AN/AX Walk 2 Slope (%)X Walk 1 Slope (%)1.8X Walk 2 Width (in)X Walk 2 Slope (%)5.8X Walk 2 X Slope (%)N/AAny Obstructions?N/AN/AClear Space to XWalk (in)N/AAny Obstructions?N/AN/AStorm Grate/Utility Type





