

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.6

0.2

N/A

Good

Main Street: POWATAN CT Intersection ID: 47441 Cross Street: KALISPELL LN Location: NW **Overall Compliance: No** ADA ID: 7217A89E48A1 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

48.0

48.0

N/A

No

To E

N/A

8.1

0.8

N/A

N/A

N/A

N/A

N/A

Flare Slope LT (%) Flare Traversable LT?

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type



KALISPELL LN Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

ונ	Possible Solution		rieia ivie
1	Possible Solutions:	Compli	ance Description
Service Services	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
1	•	Yes	Ramp Width (in)
1		N/A	Flare Type LT
		N/A	Flare Slope LT (%)
100		N/A	Flare Traversable LT
0		N/A	Landing Length (in)
	Surveyor Notes:	N/A	Landing Width (in)
-	N/A	N/A	Landing Slope (%)
į		N/A	Landing X Slope (%
1		N/A	Landing Curb? (Y/N
N.		N/A	Shared Landing?
	PROW/ADA:	N/A	Gutter Ponding?
-	Not Found, R304.2.2	N/A	Gutter Lip Ht (in)
		N/A	Painted X Walk1?
ķ			X Walk 1 Direction
		N/A	X Walk 1 Width (in)
			X Walk 1 Slope (%)
			X Walk 1 X Slope (%
		N/A	Ramp inside XWalk
			Road Slope (%)





Total Cost:



N/A

1850.00