

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10042511	Main Street: ZILKER_PARK_DR	Cross Street: N/A	Location: S
ADA ID: 7218BE192DE4	Ramp Type: Para	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 10			



Possible Solutions:

**Install Detectable Warning System.**

Surveyor Notes:

**ACCESS AISLE RAMP**

PROW/ADA:

**R305**

Total Cost: \$ 235.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	52.5	N/A	Ramp Length RT (in)	52.5
Yes	Ramp Width LT (in)	70.0	Yes	Ramp Width RT (in)	70.0
Yes	Ramp Slope LT (%)	3.3	Yes	Ramp Slope RT (%)	6.7
Yes	Ramp XSlope LT (%)	0.6	Yes	Ramp XSlope RT (%)	2.0
Yes	Landing Length (in)	75.0	No	DWS Provided?	No
Yes	Landing Width (in)	71.0	N/A	DWS Contrast?	No
Yes	Landing Slope (%)	1.7	N/A	DWS Length (in)	N/A
Yes	Landing X Slope (%)	0.4	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	Yes	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.1
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.7
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Compliant	Curb Slope (%)	5.4

