

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Surface Condition? (G/P)

Curb Slope (%)

Good

0.4

Yes

Yes

| Intersection ID: 10031496  | Main Street: MCKEE_RD  |                     |    | Cross Street: N/A                               |      |                       |       |      | Location:                   | SE   |
|--|------------------------|---------------------|----|---|------|-----------------------|-------|------|-----------------------------|------|
| ADA ID: 728333C31E48   | Ramp Type: BlendTrans2 |                     |    | Initial Pass/Fail: Pass Overall Compliance: Yes |      |                       |       |      | es Severity Score:          | 0    |
| Codes/Mitigation Info/Possible Solution  |                        |                     |    | Field Measurements/Component Compliance         |      |                       |       |      |                             |      |
|  |                        | Possible Solutions: |    |   | Comp | liance Description    | Data  | Comp | liance Description          | Data |
| and the state of the second  | Start A B              | N/A                 |    |   | N/A  | Ramp Length (in)      | 72.0  | Yes  | BlendTrans Slope (%)        | 0.6  |
| and the second |                        |                     |    |   | Yes  | Ramp Width (in)       | 70.0  | Yes  | BlendTrans XSlope (%)       | 0.4  |
| A PARTY AND A PARTY AND A PARTY  |                        |                     |    |   | N/A  | Flare Type LT         | None  | N/A  | Flare Type RT               | None |
|  |                        |                     |    |   | N/A  | Flare Slope LT (%)    | N/A   | N/A  | Flare Slope RT (%)          | N/A  |
| THE FOR  |                        |                     |    |   | N/A  | Flare Traversable LT? | N/A   | N/A  | Flare Traversable RT?       | N/A  |
| Mou  | 110                    |                     |    |   | N/A  | Landing Length (in)   | N/A   | Yes  | DWS Provided?               | Yes  |
|  | OF TRUE                | Surveyor Notes:     |    |   | N/A  | Landing Width (in)    | N/A   | Yes  | DWS Contrast?               | Yes  |
| - <u>6</u>   | A PLANT                | N/A                 |    |   | N/A  | Landing Slope (%)     | N/A   | Yes  | DWS Length (in)             | 24.0 |
| 6.   |                        | 9.<br>Al            |    |   | N/A  | Landing X Slope (%)   | N/A   | Yes  | DWS Full Width?             | Yes  |
|  | 62.0                   |                     |    |   | N/A  | Landing Curb? (Y/N)   | No    | Yes  | DWS Offset (in)             | 0.0  |
|  | the second             |                     |    |   | N/A  | Shared Landing?       | No    |      |                             |      |
|  | ALL I                  | PROW/ADA:           |    |   | Yes  | Gutter Ponding?       | No    | Yes  | Gutter Slope (%)            | 2.9  |
|  | Contraction 1          | N/A                 |    |   | Yes  | Gutter Lip Ht (in)    | 0.0   | Yes  | Gutter X Slope (%)          | 0.6  |
|  | LA SALES MARTIN        |                     |    |   | N/A  | Painted X Walk1?      | No    | N/A  | Painted X Walk2?            | N/A  |
|  | S. Saltin              |                     |    |   |      | X Walk 1 Direction    | To SW |      | X Walk 2 Direction          | N/A  |
|  |                        |                     |    |   |      | X Walk 1 Width (in)   | N/A   |      | X Walk 2 Width (in)         | N/A  |
| Street 1 Name  | ENTRANCE               |                     |    |   |      | X Walk 1 Slope (%)    | 0.4   |      | X Walk 2 Slope (%)          | N/A  |
| Stop Condition-Street 1  | None                   |                     |    |   |      | X Walk 1 X Slope (%)  | 1.0   |      | X Walk 2 X Slope (%)        | N/A  |
| Street 2 Name  | N/A                    |                     |    |   | N/A  | Ramp inside XWalk1?   | N/A   | N/A  | Ramp inside XWalk2?         | N/A  |
| Stop Condition-Street 2  | N/A                    |                     |    |   |      | Road Slope (%)        | 1.0   |      | Clear Space?                | Yes  |
|  |                        |                     |    |   |      | Road X Slope (%)      | 0.4   | N/A  | Clear Space to XWalk (in)   | N/A  |
|  |                        |                     |    |   | Yes  | Any Obstructions?     | No    | Yes  | Storm Grate/Utility Hazard? | No   |
|  |                        | Total Cost:         | \$ | 0.00  |      | Obstruction Type      |       |      | Storm Grate/Utility Type    |      |
|  |                        |                     |    |   |      |                       | N/A   |      |                             | N/A  |





