

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

58.0

36.0

3.3

1.2

4.0

1.2

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

24.6

Intersection ID: N/AMain Street:MUNSEE_STCross Street:W_SUGAR_CREEK_RDLocation:NEADA ID: 728442EE5805Ramp Type:Combination2DiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

Yes

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Curb Slope (%)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

72.0

36.0

7.4

2.9

24.5

48.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

None W SUGAR CREEK RD StopSign MUNSEE ST Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Sidewalk.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost:

Compliance Description N/A Ramp Length LT (in) No Ramp Width LT (in) Yes Ramp Slope LT (%) Ramp XSlope LT (%) No N/A Ramp Length (in) Ramp Width (in) Yes N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) Landing Width (in) N/A N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/ N/

Road X Slop

3600.00

Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	No
X Walk 1 Direction	To W		X Walk 2 Direction	To S
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	1.4
X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	2.2
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	1.8		Clear Space?	N/A
Road X Slope (%)	1.8	N/A	Clear Space to XWalk (in)	N/A
The second secon		N/A	Any Obstruction?	N/A
			Obstruction Type	
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
			Storm Grate/Utility Type	
				N/A
C TO BUILDING		Yes	Surface Condition? (G/P)	Good
	Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%)	Gutter Ponding? N/A Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) N/A	Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) Road X Slope (%) 1.8 N/A N/A N/A	Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road X Slope (%) Road X Slope (%) Road X Slope (%) N/A N/A N/A N/A Road Stope (%) 1.8 N/A N/A Road Stope (%) N/A N/A N/A Road X Slope (%) N/A N/A N/A N/A Road Stope (%) N/A N/A N/A Clear Space to XWalk (in) N/A Any Obstruction? Obstruction Type N/A Storm Grate/Utility Hazard? Storm Grate/Utility Type



