

Access Compliance Report Public Rights-of-Way (Curb Ramps)



								1	147
Intersection ID: 10011804	ntersection ID: 10011804 Main Street: MASONIC_DR		Cross Street: N/A					Location:	W
ADA ID: 72A1811D5838 Ramp Type: BlendTrans2			Initial Pass/Fail: Pass Overall Compliance: No					o Severity Score:	17.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A ST R	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Install Detectable Warning Syste	em.	N/A	Ramp Length (in)	87.0	Yes	BlendTrans Slope (%)	2.3
	MPA STORES	Grind Gutter Lip.		Yes	Ramp Width (in)	120.0	Yes	BlendTrans XSlope (%)	1.1
				N/A	Flare Type LT	None	N/A	Flare Type RT	None
	Sale as			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Senter Contraction of the		8		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	No	DWS Provided?	No
	a the	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	No
K C	<u>k.</u>	NO CURB		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
	20			N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			N/A	Shared Landing?	No			
	Lange -	PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.3
The second second	A REAL PROPERTY AND A REAL	R305, R302.7.2		No	Gutter Lip Ht (in)	0.3	Yes	Gutter X Slope (%)	0.4
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	MASONIC DR				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	0.3		Clear Space?	Yes
					Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	435.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

N/A