## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10039889	on ID: 10039889 Main Street: TRADE_PARK_CT		Cross Street: N/A			Location:	SW		
ADA ID: 72C8A6AF98C3 Ramp Type: PerpDiag		/pe: PerpDiag	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	12/	Possible Solutions:	Comp	Compliance Description Data		Compliance Description		Data	
0.0		Remove & Replace Curb Ramp Wi	ith N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	11.1	
		Two New Directional Ramps or Equivalent.	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.1	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
A BALL CALL STALL	3 64		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	4		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	- 1/2	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
La States		N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	St Ba		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
······································	2312		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
		PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To E		X Walk 2 Direction	To N	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name T	RADE PARK CT			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	3.1	
Stop Condition-Street 2	None			X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	2.8	
Street 2 Name	ENTRANCE		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None			Road Slope (%)	1.0	N/A	Clear Space?	N/A	
				Road X Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 320	00.00	Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	
						Yes	Surface Condition? (G/P)	Good	





