


Access Compliance Report Public Rights-of-Way (Curb Ramps)

Intersection ID: 48602 Main Street: S_TRYON_ST Cross Street: GRANDIFLORA_DR Location: NW

ADA ID: 72EF6A05D99A Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.1, R304.2.2, R304.5.3

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|-------|------------|-----------------------------|-------|
| N/A | Ramp Length (in) | 95.0 | No | Ramp Slope (%) | 8.9 |
| No | Ramp Width (in) | 47.5 | No | Ramp XSlope (%) | 6.1 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | Yes |
| | X Walk 1 Direction | To SE | | X Walk 2 Direction | To NE |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | 74.0 |
| | X Walk 1 Slope (%) | 1.6 | | X Walk 2 Slope (%) | 2.0 |
| | X Walk 1 X Slope (%) | 3.8 | | X Walk 2 X Slope (%) | 0.9 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | Yes |
| | Road Slope (%) | 3.0 | N/A | Clear Space? | N/A |
| | Road X Slope (%) | 1.6 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |

Total Cost: \$ 3200.00

Street 1 Name S TRYON ST
 Stop Condition-Street 2 None
 Street 2 Name GRANDIFLORA DR
 Stop Condition-Street 1 StopSign

