

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11308	Main Street: CARDIFF_AV	Cross Street: SPRINGWAY_DR	Location: NE
ADA ID: 72EFC03071FC	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
 Street 1 Name CARDIFF AV Stop Condition-Street 1 StopSign Street 2 Name SPRINGWAY DR Stop Condition-Street 2 None	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	71.0	Yes	BlendTrans Slope (%)	3.7
			No	Ramp Width (in)	42.0	Yes	BlendTrans XSlope (%)	1.4
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	7.1		X Walk 2 Slope (%)	6.9	
			X Walk 1 X Slope (%)	6.2		X Walk 2 X Slope (%)	6.5	
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	2.3		Clear Space?	N/A			
	Road X Slope (%)	9.2	N/A	Clear Space to XWalk (in)	N/A			
	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
		Yes		Surface Condition? (G/P)	Good			
		No		Curb Slope (%)	15.6			
					</			