

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10023798 Main Street: COLONY_RD Cross Street: FAIRINGTON_APARTMENTS_DR Location: SE

ADA ID: 72FFA9D6A9AA Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name FAIRINGTON APARTMENTS DR
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Possible Solution		Field Measurements/Component Compilance					
Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
Remove & Replace Entire F	Ramp.	N/A	Ramp Length (in)	84.0	N/A	Grade Break?	N/A
•	•	Yes	Ramp Width (in)	71.0	N/A	Grade Break Slope (%)	0.0
		Yes	Ramp Slope (%)	5.0	N/A	Grade Break XSlope (%)	0.0
		No	Ramp XSlope (%)	3.2			
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No		Road Slope (%)	4.6
			X Walk 1 Direction	To N		Road X Slope (%)	2.0
			X Walk 1 Width (in)	N/A		Clear Space?	N/A
			X Walk 1 Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A
			X Walk 1 X Slope (%)	2.0	N/A	Storm Grate/Utility Hazard?	N/A
		N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
		N/A	Any Obstructions?	N/A			N/A
Total Cost:	\$ 1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
				N/A	N/A	Curb Slope (%)	2.1
					-		





