

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Good

Storm Grate/Utility Type

Surface Condition? (G/P)

Intersection ID: 14839 Main Street: BEULAH AV Cross Street: W TYVOLA RD Location:

ADA ID: 7339EAC24E02 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 58.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 W TYVOLA RD None **BEULAH AV** StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: R304.5.1, R304.2.2, R304.5.3

Total Cost: 3200.00

ried Measurements/Component Comphance						
	Compliance Description		Data	Compliance Description		Data
	N/A	Ramp Length (in)	54.0	No	Ramp Slope (%)	15.8
	No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	7.0
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	1.1
		X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	3.9
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	4.4	N/A	Clear Space?	N/A
		Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A

N/A







Obstruction Type