## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13680	ersection ID: 13680 Main Street: MORRIS_FIELD_DR Cross Street: AIRPORT_DR							Location:	SE
ADA ID: 739270CD3B48	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No					
· · · · ·									21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
AIRPORT DIS		Possible Solutions:		Compliance Description D		Data	ta Compliance Description		Data
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	46.5	No	Ramp Slope (%)	11.3
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	0.1
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
and the second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
MORRIS FLE				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
<u>6</u>	parante Sign -			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
B I	the ward			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	A low to may	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	- 27	R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To N		X Walk 2 Direction	To W	
A Providence of the second sec				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	MORRIS FIELD DR				X Walk 1 Slope (%)	7.3		X Walk 2 Slope (%)	4.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.6		X Walk 2 X Slope (%)	5.0
Street 2 Name	AIRPORT DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.4	N/A	Clear Space?	N/A
					Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							1		

Yes Surface Condition? (G/P)

Good

