## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: GLENBURN_LN		Cross S	Street:	MOSSDALE_LN	Location:	NW		
ADA ID: 739E24663A17	I7 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	26.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Compli			liance Description	Data	
		Remove & Replace Curb Ramp	Nith	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	12.9
		Two New Directional Ramps or		Yes	Ramp Width (in)	50.0	No	Ramp XSlope (%)	3.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the cost of the		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
CLIENBURNILM	G.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6.	6	-		N/A	Shared Landing?	N/A			
- The second second		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	it the sea	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A CONTRACTOR OF A CONTRACTOR OFTA CONTRACTOR O				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GLENBURN LN				X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	0.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	3.1
Street 2 Name	MOSSDALE LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.7	N/A	Clear Space?	N/A
					Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

