

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



									/	
Intersection ID: 32292	Main Sti	reet: OLD_ARDREY_KELL_RD	Cross	Street:	HONEYNUT_DR	Location:	NE			
ADA ID: 73FBD17CF6F8	Ramp T	Ramp Type: Perp			ail: Fail Overall	nce: N	o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description			
A State of the sta	NA 38 11	Remove & Replace Entire Ram	p.	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	9.8	
	8 81 11		P -	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.9	
	S # 11 /			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A A A A A A A A A A A A A A A A A A A		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
6 59	6 9 / / /			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	12 1			N/A	Shared Landing?	N/A				
5	1 Parts	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
1 PH I CARD		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
SI / / / / / / / / / / / / / / / / / / /	1 test			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
	114 1			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	OLD ARDREY KELL RD	_			X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							•			

Yes Surface Condition? (G/P)

Good

