

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28377 Main Street: CORNWALLIS\_HALL\_DR Cross Street: ROYAL\_HIGHLANDS\_CT Location: SE

ADA ID: 74092D8D5820 Ramp Type: Perp Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 2.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
CORNWALLIS HALL DR
Stop Condition-Street 2
StopSign
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/A Ramp Length (in)
Yes Ramp Width (in)
N/A Flare Type LT
N/A Flare Slope LT (%)
N/A Flare Traversable L
No Landing Length (in)

Surveyor Notes:

Yes Landing Width (in)
N/A Shared Landing?
PROW/ADA:

PROW/ADA:

R304.2.1, R304.2.2-Perp, R304.3.2Para, R304.2.3, R305.2

Para, R304.2.3, R305.2

PARAMALE Compliance Description
N/A Ramp inside XWalk 1

,,		
		N/A
		N/A
Total Cost:	\$ 1850.00	Yes
14		

Compl	iance Description	Data	Comp	liance Description	Data
N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.2
Yes	Ramp Width (in)	50.0	Yes	Ramp XSlope (%)	0.1
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	6.1	No	Flare Slope RT (%)	10.4
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
No	Landing Length (in)	47.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	2.1	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.2	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	2.5
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.9
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.9
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





