


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9060	Main Street: DUNDEEN_ST	Cross Street: REDBUD_ST	Location: SE
ADA ID: 74108607C537	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	36.0	N/A	Ramp Length RT (in)	36.0
			Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	60.0
			No	Ramp Slope LT (%)	13.1	Yes	Ramp Slope RT (%)	1.3
			Yes	Ramp XSlope LT (%)	1.7	No	Ramp XSlope RT (%)	2.3
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Surveyor Notes:								
RT RP < 5%								
PROW/ADA:								
R304.3.2, R304.5.3								

