


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 19432	Main Street: REXFORD_RD	Cross Street: COCA-COLA PLAZA	Location: SW
ADA ID: 744BA4EF0E01	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 27.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance								
	Possible Solutions:		Compliance			Description			Data		
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		122.0	Yes	Ramp Slope (%)		5.4	
			Yes	Ramp Width (in)		48.0	No	Ramp XSlope (%)		5.1	
			N/A	Flare Type LT		N/A	N/A	Flare Type RT		N/A	
			N/A	Flare Slope LT (%)		N/A	N/A	Flare Slope RT (%)		N/A	
			N/A	Flare Traversable LT?		N/A	N/A	Flare Traversable RT?		N/A	
			N/A	Landing Length (in)		N/A	N/A	DWS Provided?		N/A	
			N/A	Landing Width (in)		N/A	N/A	DWS Contrast?		N/A	
			N/A	Landing Slope (%)		N/A	N/A	DWS Length (in)		N/A	
			N/A	Landing X Slope (%)		N/A	N/A	DWS Full Width?		N/A	
		N/A	Landing Curb? (Y/N)		N/A	N/A	DWS Offset (in)		N/A		
		N/A	Shared Landing?		N/A						
		N/A	Gutter Ponding?		N/A	N/A	Gutter Slope (%)		N/A		
		N/A	Gutter Lip Ht (in)		N/A	N/A	Gutter X Slope (%)		N/A		
		N/A	Painted X Walk1?		No	N/A	Painted X Walk2?		N/A		
			X Walk 1 Direction		To E		X Walk 2 Direction		N/A		
		N/A	X Walk 1 Width (in)		N/A	N/A	X Walk 2 Width (in)		N/A		
			X Walk 1 Slope (%)		2.2		X Walk 2 Slope (%)		N/A		
			X Walk 1 X Slope (%)		2.9		X Walk 2 X Slope (%)		N/A		
		N/A	Ramp inside XWalk1?		N/A	N/A	Ramp inside XWalk2?		N/A		
			Road Slope (%)		N/A	N/A	Clear Space?		N/A		
			Road X Slope (%)		N/A	N/A	Clear Space to XWalk (in)		N/A		
		N/A	Any Obstructions?		N/A	N/A	Storm Grate/Utility Hazard?		N/A		
			Obstruction Type				Storm Grate/Utility Type				
						N/A			N/A		
						No	Surface Condition? (G/P)		Poor		

