

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10025452		Main Street: E_INDEPENDENCE_BV		Cross Street: N/A		Location:		NW			
ADA ID: 745D704A8E77		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 5			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
 <p>Street 1 NameENTRANCE</p> <p>Stop Condition-Street 1None</p> <p>Street 2 NameN/A</p> <p>Stop Condition-Street 2N/A</p>				Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
				Remove & Replace Entire Ramp. Remove & Replace Gutter.		N/A	Ramp Length (in)	31.0	Yes	Grade Break?	Yes
						Yes	Ramp Width (in)	60.0	No	Grade Break Slope (%)	9.1
						Yes	Ramp Slope (%)	6.6	Yes	Grade Break XSlope (%)	0.7
						Yes	Ramp XSlope (%)	2.0			
						N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
						N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
						N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
						Yes	Landing Length (in)	65.0	Yes	DWS Provided?	Yes
						Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes
		No	Landing Slope (%)	2.1	Yes	DWS Length (in)	24.0				
		Yes	Landing X Slope (%)	1.4	Yes	DWS Full Width?	Yes				
		N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	23.0				
		N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	0.0				
		Yes	Gutter Ponding?	No	No	Gutter Slope (%)	5.7				
		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	2.1				
		N/A	Painted X Walk1?	No		Road Slope (%)	0.8				
			X Walk 1 Direction	To SE		Road X Slope (%)	2.6				
			X Walk 1 Width (in)	N/A		Clear Space?	Yes				
			X Walk 1 Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A				
			X Walk 1 X Slope (%)	2.6	Yes	Storm Grate/Utility Hazard?	No				
		N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type					
		Yes	Any Obstructions?	No			N/A				
			Obstruction Type		Yes	Surface Condition? (G/P)	Good				
					N/A	Curb Slope (%)	11.7				
		Total Cost:		\$	2350.00						

