

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 4155	Main Str	ANDEW LAMES DD	Cross Str	io oti	OVERLOOK_MOUNT			Location:	NW
		Main Street: ANDREW_JAMES_DR							
ADA ID: 745E1E033C5C Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
Alexand Ale Ale		Possible Solutions:	Compliance Description			Data Compliance Description			Data
the second second		Remove & Replace Entire Ramp	. N	I/A	Ramp Length (in)	44.0	No	Ramp Slope (%)	18.4
	2/		Y	′es	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.4
	Al As		N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the sales			Ν	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	3/		Ν	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	4 personal a		Ν	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
AND		N/A	Ν	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Allon -	1-1-C-1-10		Ν	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Section 1	6.		N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
ACTION S	<u>03</u>		N	I/A	Shared Landing?	N/A			
AND HERE TO AND		PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A State	R304.2.2	N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	AND THE REAL		Ν	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
AND STREET STREET STREET	A STATE OF THE STA				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
		Ν	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name AND	REW JAMES DR				X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		Ν	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Ν	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

