

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

25.5

47.5

1.3

11.8

9.7

0.3

N/A

No

N/A

4.3

8.0

N/A

N/A

To NW

Main Street: PONDELLA DR Intersection ID: N/A **Cross Street: SPRING GARDEN LN** Location: S **Overall Compliance: No Severity Score:** 0 ADA ID: 746049C6CD43 Ramp Type: Combination2Diag Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign **SPRING GARDEN LN** None PONDELLA DR Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.1, R304.2.2, R304.5.3

Total Cost: 3200.00 Compliance Description Data Compliance Description Ramp Length LT (in) N/A N/A 27.0 Ramp Length RT (in) No Yes Ramp Width LT (in) 48.0 Ramp Width RT (in) Yes Ramp Slope LT (%) 6.3 Yes Ramp Slope RT (%) Ramp XSlope LT (%) No Ramp XSlope RT (%) No 9.1 N/A Ramp Length (in) 46.5 Nο Ramp Slope (%) Ramp Width (in) 46.5 Yes Ramp XSlope (%) No N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To NE X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in)

1.6

0.5

N/A

0.6

N/A

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)







N/A

1.8	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstruction?	N/A
		Obstruction Type	
			N/A
	N/A	Storm Grate/Utility Hazard?	N/A
		Storm Grate/Utility Type	
			N/A
	Yes	Surface Condition? (G/P)	Good
		Curb Slope (%)	36.0

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?