

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

5.9

8.0

N/A

No

To SE

N/A

3.7

1.5

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 14024 Main Street: BASCOM ST **Cross Street: CHESTERFIELD AV** Location: Ν **Overall Compliance: No Severity Score:** ADA ID: 7486CB004A50 Ramp Type: PerpDiag Initial Pass/Fail: Fail 8.75

**Codes/Mitigation Info/Possible Solution** 

Equivalent.

## Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Flare Traversable RT?

Data

66.5

46.0

N/A

1.0

No

N/A

0.7

0.9

To SW



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 Surveyor Notes: N/A PROW/ADA: R304.5.1

**CHESTERFIELD AV** StopSign **BASCOM ST** None

> Total Cost: 3200.00

Remove & Replace Curb Ramp With Two New Directional Ramps or

Compliance Description N/A No N/A N/A

X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

Flare Traversable LT?

Flare Type LT

Any Obstructions? **Obstruction Type** 

N/A N/A Ramp inside XWalk2? 1.9 N/A Clear Space? N/A 1.9 Clear Space to XWalk (in) N/A N/A Storm Grate/Utility Hazard? Storm Grate/Utility Type N/A

Surface Condition? (G/P)







N/A