

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4219 Main St		eet: DAVIS_LAKE_PY	Cross	s Street:	Street: UNIVERSITY_STATION_			Location:	NE
ADA ID: 74A607D1A3D0 Ramp T		Type: Directional1		Initial Pass/Fail: Fail Overall		Compliance: No		o Severity Score:	26.25
	/Possible Solution			Field Measu	nent Compliance				
		Possible Solutions:		Comp	bliance Description	Data	Comp	liance Description	Data
		Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	57.0	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	50.0	N/A	Grade Break Slope (%)	0.0
				No	Ramp Slope (%)	13.4	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	2.7			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	a B	1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	WINESEIN STATION SR	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	5 RESULT Sterne	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
E.	WINA			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
143	E.			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
Ŀ.		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	X .	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	\backslash	,		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	\mathbf{X}			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	\mathbf{X}			N/A	Painted X Walk1?	No		Road Slope (%)	4.0
Street 1 Name	UNIVERSITY STATION CR	_			X Walk 1 Direction	To SE		Road X Slope (%)	4.9
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	4.0	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.9	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	N/A

