

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15124	Main Street: CHEROKEE_RD			Cross Street: S_LAUREL_AV				Location:	E
ADA ID: 74F003DD8B1B Ramp Type: Perp		Init	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	4	Possible Solutions:		Compliance Description			Data Compliance Description		
A FALA F	10	Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	73.0	No	Ramp Slope (%)	8.6
23 125 34 12	L'AR .		•	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.2
AT ALL THE MALL THE	ŧ,			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Stand and a stand			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
1 11 20 20	and the second s			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
and be the second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
3 LAU		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second secon		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6	11 - 19 - 1820			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
CHEROKEE_RD				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the balance	A STREET			N/A	Shared Landing?	N/A			
CONTRACTOR OF THE OWNER OF THE OWNER OF	PAR PROPERTY OF	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	So The R	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	9-14			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name S LA	AUREL AV				X Walk 1 Slope (%)	10.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.0	ס	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

Surface Condition? (G/P)

Good