

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 44242 Main Street: KIEV DR Cross Street: SUNSET\_RD Location: NW **Overall Compliance: No** ADA ID: 74FD654BF557 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 21.25

Codes/Mitigation Info/Possible Solution



**KIEV DR** Street 1 Name StopSign Stop Condition-Street 2 Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solution	
Possible Solutions:	(
Remove & Replace Entire Ramp.	N
·	N
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
R304.5.1, R304.2.2	N
,	N
	1

Total Cost:



1850.00

Field Measurements/Component Compliance								
Compl	iance Description	Data	Compl	iance	Description	Data		
N/A	Ramp Length (in)	48.0	No	Ram	Slope (%)	8.7		
No	Ramp Width (in)	42.0	Yes	Ramp	XSlope (%)	0.4		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To E		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.9		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.2		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		
	<b>建</b> 网络							