

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10936	Main Street: LITTLE ROCK RD	Cross Street: SCOTT FUTRELL DR	Location: SE
ADA ID: 75448B28647D	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 0.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Restripe Crosswalk(s) To Provide Clear space.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, Not Found

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	63.5	N/A	Ramp Length RT (in)	66.0
Yes	Ramp Width LT (in)	67.0	Yes	Ramp Width RT (in)	67.0
Yes	Ramp Slope LT (%)	7.0	Yes	Ramp Slope RT (%)	5.1
No	Ramp XSlope LT (%)	2.4	No	Ramp XSlope RT (%)	2.1
Yes	Landing Length (in)	67.0	Yes	DWS Provided?	Yes
No	Landing Width (in)	47.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	3.5	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.5	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.3
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.6
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To N		X Walk 2 Direction	To W
N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	110.0
	X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	0.1
	X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	1.6
Yes	Ramp inside XWalk1?	Yes	Yes	Ramp inside XWalk2?	Yes
	Road Slope (%)	0.5	N/A	Clear Space?	Yes
	Road X Slope (%)	1.0	No	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	7.2

Total Cost: \$ 3700.00

