

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

35.0

42.0

1.6

4.9

6.8

4.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: FONTANA_AV Intersection ID: 10000 **Cross Street: WHISNANT ST** Location: NE Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5 **ADA ID: 7550CC0DDFEA** Ramp Type: Combination2

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

43.0

51.0

8.4

2.7

59.0

47.1

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign **FONTANA AV** Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes No No N/A No Surveyor Notes: N/A RT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3, N/A R304.3.2 N/A N/A N/A

Total Cost:



1600.00

11/	Gutter i Origing:	17/7	17/7	Gutter Glope (70)	IV/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	The state of the s		N/A	Any Obstruction?	N/A
				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			l	Storm Grate/Utility Type	147.1
					N/A
			Yes	Surface Condition? (G/P)	Good
			l	Curb Slope (%)	18.3