cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•							
Intersection ID: 49920	section ID: 49920 Main Street: AUSTIN_DEKOTA_DR Cros				WANAMASSA_DR	Location:	Е		
ADA ID: 75ACF77781A4	Ramp Ty	Ramp Type: PerpDiag Initia			al Pass/Fail: Pass Overall Compliance: No			o Severity Score:	0
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
15-11-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ramp Two New Directional Ramps or Equivalent.	p With	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	6.9
			•	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.1
				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	7.6	N/A	Flare Slope RT (%)	7.2
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
				Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
6		Surveyor Notes:		Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
A Room		N/A		No	Landing Slope (%)	3.0	Yes	DWS Length (in)	24.5
BAR BAR BAR				Yes	Landing X Slope (%)	0.3	Yes	DWS Full Width?	Yes
A A A A A A A A A A A A A A A A A A A				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.5
	A CONTRACTOR	1		N/A	Shared Landing?	No			
	New /	PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.7
and the AS	CALL O	Not Found, R304.2.2-Perp, R	04.3.2-	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.2
	A Contra	Para, R305.2	•	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
and the second	130	, i i i i i i i i i i i i i i i i i i i			X Walk 1 Direction	To NW		X Walk 2 Direction	To E
	V / Am			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	WANAMASSA DR	-			X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	0.9
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	2.0
Street 2 Name	AUSTIN DEKOTA DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	0.3	N/A	Clear Space?	Yes
					Road X Slope (%)	1.4	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

