

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

52.5

59.5

5.8

1.4

6.1

0.6

N/A

N/A

N/A

N/A

N/A

N/A

17.0

Cross Street: N/A Intersection ID: 9231 Main Street: THE PLAZA Location: SW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 75B0C2C39E38 Ramp Type: Combination2 **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

D14/0 E 11 14/2 11/1 0

Curb Slope (%)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

55.5

60.0

0.9

1.7

47.5

47.5

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name None THE PLAZA Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. N/A N/A N/A N/A No Surveyor Notes: N/A LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1 N/A N/A N/A N/A N/A N/A



Total Cost:



N/A

1600.00

Landing X Slope (%)		N/A	N/A	DWS Full Width?	N/A
Landing Curb	? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landi	ing?	N/A			
Gutter Pondir	ng?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht	(in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Wa	alk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Dire	ection	To N		X Walk 2 Direction	N/A
X Walk 1 Wid	lth (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slop	oe (%)	0.7		X Walk 2 Slope (%)	N/A
X Walk 1 X S	lope (%)	2.3		X Walk 2 X Slope (%)	N/A
Ramp inside	XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope	⊖ (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	14,7 1
					N/A
			Yes	Surface Condition? (G/P)	Good
	63				