

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 10033044	Main Street: NOLLEY_CT			Street:	N/A	Location:	SW		
ADA ID: 7651BFD5511B	D: 7651BFD5511B Ramp Type: Perp			Pass/Fa	ail: Fail Overall	o Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:					liance Description	Data	
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	93.0	Yes	Ramp Slope (%)	5.2
				No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.0
- Contract 1 1 - The				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
6. K	and the second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E &		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	ALCO			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	and the second			N/A	Shared Landing?	N/A			
Mandura and a fit	2 they are	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A.C.	R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Letter and L				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	Mar 1				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
a the the second and a second a				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	NOLLEY CT				X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A