

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52449 Main Street: TRANQUIL_OAK_PL Cross Street: PAT_GARRETT_ST Location: NE **Overall Compliance: No** ADA ID: 768CED0677BC Ramp Type: Directional1 Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



PAT GARRETT ST Street 1 Name Stop Condition-Street 1 None Street 2 Name N/A Stop Condition-Street 2 N/A

1	Possible Solutions:
	Remove & Replace Entire Ramp.
-	Surveyor Notes:
()	N/A
	PROW/ADA:
The second second second	R304.2.2

		N/A
Surveyor Notes:		N/A
N/A		N/A
		N/A
		N/A
		N/A
PROW/ADA:		N/A
R304.2.2		N/A
		N/A
		N/A
Total Cost:	\$ 1600.00	

Compliance Description		Data	Compl	iance	Description	Data
N/A	Ramp Length (in)	70.0	N/A	Grad	e Break?	N/A
Yes	Ramp Width (in)	67.0	N/A	Grad	e Break Slope (%)	0.0
No	Ramp Slope (%)	9.8	N/A	Grad	e Break XSlope (%)	0.0
Yes	Ramp XSlope (%)	3.0				
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	0.0	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	0.0	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	0.0	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A
N/A	Shared Landing?	N/A	N/A	DWS	Offset RT (in)	N/A
N/A	Gutter Ponding?	0.0	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No		Road	Slope (%)	1.6
	X Walk 1 Direction	To S		Road	X Slope (%)	3.6
	X Walk 1 Width (in)	N/A		Clear	Space?	N/A
	X Walk 1 Slope (%)	1.6	N/A	Clear	Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	3.6	N/A	Storn	n Grate/Utility Hazard?	N/A
N/A	Ramp inside XWalk1?	N/A		Storn	n Grate/Utility Type	
N/A	Any Obstructions?	N/A				N/A
	Obstruction Type		Yes	Surfa	ce Condition? (G/P)	Good
		N/A	N/A	Curb	Slope (%)	3.2





