cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040944	Main Street: WALNUT_AV			ss Street:	: N/A	Location:	SE		
ADA ID: 77159B3F5491	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Compliance			liance Description	Data	
5	d at	Remove & Replace Entire Rar	np.	N/A	Ramp Length (in)	76.0	No	Ramp Slope (%)	9.3
		-	•	Yes	Ramp Width (in)	126.0	Yes	Ramp XSlope (%)	3.1
A A	The states			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Ser.	2		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A A A				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E C		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1111	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	B. C. C.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Non and a second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A STATISTICS .				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	1.5	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
			N/A	X Walk 1 Width (in)	120.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	WALNUT AV				X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes

Surface Condition? (G/P)

Good

