


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                       |                      |                                    |                        |
|-----------------------|----------------------|------------------------------------|------------------------|
| Intersection ID: 8303 | Main Street: IRMA_ST | Cross Street: CATHERINE_SIMMONS_AV | Location: NE           |
| ADA ID: 771C974FB86C  | Ramp Type: PerpDiag  | Initial Pass/Fail: Fail            | Overall Compliance: No |
|                       |                      | Severity Score: 33.75              |                        |

| Codes/Mitigation Info/Possible Solution  |   | Field Measurements/Component Compliance |                       |             |                   |                             |             |
|--|---|---|-----------------------|-------------|-------------------|-----------------------------|-------------|
|  | <p>Possible Solutions:</p> <p><b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b></p> | <b>Compliance</b>                       | <b>Description</b>    | <b>Data</b> | <b>Compliance</b> | <b>Description</b>          | <b>Data</b> |
|  | <p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>R304.5.1, R304.5.3</b></p>                            | N/A                                     | Ramp Length (in)      | 55.5        | Yes               | Ramp Slope (%)              | 6.2         |
|  |   | No                                      | Ramp Width (in)       | 44.0        | No                | Ramp XSlope (%)             | 11.6        |
|  |   | N/A                                     | Flare Type LT         | N/A         | N/A               | Flare Type RT               | N/A         |
|  |   | N/A                                     | Flare Slope LT (%)    | N/A         | N/A               | Flare Slope RT (%)          | N/A         |
|  |   | N/A                                     | Flare Traversable LT? | N/A         | N/A               | Flare Traversable RT?       | N/A         |
|  |   | N/A                                     | Landing Length (in)   | N/A         | N/A               | DWS Provided?               | N/A         |
|  |   | N/A                                     | Landing Width (in)    | N/A         | N/A               | DWS Contrast?               | N/A         |
|  |   | N/A                                     | Landing Slope (%)     | N/A         | N/A               | DWS Length (in)             | N/A         |
|  |   | N/A                                     | Landing X Slope (%)   | N/A         | N/A               | DWS Full Width?             | N/A         |
|  |   | N/A                                     | Landing Curb? (Y/N)   | N/A         | N/A               | DWS Offset (in)             | N/A         |
|  |   | N/A                                     | Shared Landing?       | N/A         |                   |                             |             |
|  |   | N/A                                     | Gutter Ponding?       | N/A         | N/A               | Gutter Slope (%)            | N/A         |
|  |   | N/A                                     | Gutter Lip Ht (in)    | N/A         | N/A               | Gutter X Slope (%)          | N/A         |
|  |   | N/A                                     | Painted X Walk1?      | No          | N/A               | Painted X Walk2?            | No          |
|  |   |   | X Walk 1 Direction    | To W        |                   | X Walk 2 Direction          | To S        |
|  |   | N/A                                     | X Walk 1 Width (in)   | N/A         | N/A               | X Walk 2 Width (in)         | N/A         |
|  |   |   | X Walk 1 Slope (%)    | 2.8         |                   | X Walk 2 Slope (%)          | 1.6         |
|  |   |   | X Walk 1 X Slope (%)  | 7.6         |                   | X Walk 2 X Slope (%)        | 3.3         |
|  |   | N/A                                     | Ramp inside XWalk1?   | N/A         | N/A               | Ramp inside XWalk2?         | N/A         |
|  |   |   | Road Slope (%)        | 6.2         | N/A               | Clear Space?                | N/A         |
|  |   |   | Road X Slope (%)      | 0.2         | N/A               | Clear Space to XWalk (in)   | N/A         |
|  |   | N/A                                     | Any Obstructions?     | N/A         | N/A               | Storm Grate/Utility Hazard? | N/A         |
|  |   |   | Obstruction Type      |             |                   | Storm Grate/Utility Type    |             |
|  |   |   |                       | N/A         |                   |                             | N/A         |
|  |   |   |                       |             | Yes               | Surface Condition? (G/P)    | Good        |

Total Cost: \$ 3200.00

