cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43504	Main Street: PRESCOTT_HILL_AV			Cross Street: CHESLEY_DR				Location:	NW	
ADA ID: 77295E620458	8 Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	R C	Possible Solutions:		Compliance Description		Data Compliance Desc			Data	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	44.0	No	Ramp Slope (%)	10.7	
		Two New Directional Ramps or	•••icii	No	Ramp Width (in)	39.0	No	Ramp XSlope (%)	6.5	
2 1 12		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
6				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
L.	6.			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
, PRESCOTT	Litter Carl			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
P	a d.			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
alter and the little	LE LEES			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	S States	Not Found, R304.5.1, R304.2.2 R304.5.3	2,	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Contraction of the second				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To SE		X Walk 2 Direction	To E	
	CHE TO THE M			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	PRESCOTT HILL AV	-			X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	3.2	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	0.4	
Street 2 Name	CHESLEY DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign				Road Slope (%)	3.5	N/A	Clear Space?	N/A	
					Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
4										

s Surface Condition? (G/P)

Good

